



Photo No.: Photos-20180515-175427.jpg
Description: Outlet



Photo No.: Photos-20180515-175445.jpg
Description: Downstream



Photo No.: Photos-20180515-175517.jpg
Description: Upstream



Photo No.: Photos-20180515-175536.jpg
Description: Inlet

Crossing ID: WC_0854

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 15, 2018

Watercourse Name: Atim Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 303,522 | **Northing:** 5,930,908

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 3m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Erosion at Site: No

Structural Problems: None

Culvert(s) Diameter: 1) 1.5 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 100%

Culvert Slope: level and uniform

Outlet Gap: none

Embedded?: no

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Low

Comments: Quad roads on either side of creek. This culvert is within an acreage community.

Crossing ID: WC_0866

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180515-171829.jpg
Description: Upstream

Photo No.: Photos-20180515-171852.jpg
Description: Inlet



Photo No.: Photos-20180515-171926.jpg
Description: Downstream



Photo No.: Photos-20180515-171945.jpg
Description: Outlet

Crossing ID: WC_0866

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 09, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 635,312 | **Northing:** 5,931,396

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 2.5m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 5 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition but materials eroding from the side

Armour: Riprap

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: **Low**

Comments: Area of secondary inflow has brought material to in front of wingwall.

Crossing ID: WC_0867



Photo No.: Photos-20180509-171805.jpg
Description: Upstream



Photo No.: Photos-20180509-171822.jpg
Description: Downstream



Photo No.: Photos-20180509-171900.jpg
Description: Outlet



Photo No.: Photos-20180509-171952.jpg
Description: Deck



Photo No.: Photos-20180509-172038.jpg
Description: Inlet



Photo No.: Photos-20180509-172106.jpg
Description: Secondary inflow

Crossing ID: WC_0867

NSWA Sturgeon River Watercourse Assessment

Appendix 4: Medium Risk Watercourse Crossing Overview Map and Field Sheets

NWSA Sturgeon River Study

Water Course Crossing

Risk Assessment






● Medium

Source: Contains information licensed under the Open Government Licenses - Canada and Alberta, Parkland County, City of Edmonton, Stony Plain, Strathcona County and Leduc
 Imagery acquisition date: 2001 - 2016
 Coordinates system: NAD 1983 UTM Zone 11N

1:400,000



Date: January 15, 2019
 Prepared by: G. Couture





Inspection Date: May 10, 2018

Watercourse Name: Riviere Qui Barre

GPS Co-ordinates:

UTM: 12 | **Easting:** 304,972 | **Northing:** 5,978,708

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 6m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 8 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Cause of blockage: Debris

Structural Problems: Yes- Road fill to bridge deck is lower than deck

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Fence in water at outlet, possibility to create blockage. This crossing was not part of the initial assessment, however it was included. Landowner near by mentioned the bridge and said it was upgraded winter 2017-2018. Capacity of bridge has been reached and difficult to determine structural integrity. Bridge deck is higher than road, causing a dangerous bump when driving over the bridge.

Crossing ID: WC_000a



Photo No.: Photos-20180508-182539.jpg
Description: Upstream



Photo No.: Photos-20180508-182524.jpg
Description: Inlet



Photo No.: Photos-20180508-182600.jpg
Description: Deck



Photo No.: Photos-20180508-182656.jpg
Description: Downstream




Photo No.: Photos-20180508-182809.jpg
Description: road and bridge deck not even



Photo No.: Photos-20180508-182614.jpg
Description: Outlet

Crossing ID: WC_000a

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 07, 2018

Watercourse Name: Little Egg Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 320,136 | **Northing:** 5,981,337

Stream Classification: Non-Fluvial

Bankfull Width: 3m (Estimated to Nearest Metre)

Crossing Type: Culvert - Multiple

Erosion at Site: No

Culvert(s) Diameter: 1) 0.82 m
2) 0.74 m

Greater than 10% of the culvert diameter blocked by debris?: Yes

Substrate in Culvert?: Unknown **Substrate Type:** Unknown

For what length of culvert?: unknown

What proportion has backwater?: 25%

Culvert Slope: Level and uniform

Outlet Gap: None **Embedded?:** No

Pool Depth: 0.68m and 0.81m **Scour pool apparent?:** Yes

Structural Problems: Yes, culverts are undersized and damaged.

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: cultivated field "upstream" had serious flooding this year (as per land owner said). there was water vortices's trying to drain water from the area. landowner said a third or larger culverts should be there. 2/4 culverts damaged. Vegetation at inlet causing blockage. No defined channel upstream of culverts. Area seems more of a storm water catchment.

Crossing ID: WC_0001



Photo No.: Photos-20180507-154013.jpg
Description: Downstream



Photo No.: Photos-20180507-154110.jpg
Description: Outlet - West



Photo No.: Photos-20180507-154146.jpg
Description: Outlet East



Photo No.: Photos-20180507-154340.jpg
Description: Upstream



Photo No.: Photos-20180507-154401.jpg
Description: Inlet

Crossing ID: WC_0001

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 08, 2018

Watercourse Name: Riviere Qui Barre

GPS Co-ordinates:

UTM: 12 | **Easting:** 304,018 | **Northing:** 5,981,940

Stream Classification: Non-Fluvial (Permanent - Small)

Bankfull Width: 1.5m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single **Culvert(s) Diameter:** 1.19 m

Erosion at Site Potential

Erosion Location (Inlet or Outlet): Both

Erosion Source: Bank Slump, Ditch Gully

Erosion Extent: Low **Total Erosion Area:** 3 m²

Greater than 10% of the culvert diameter blocked by debris?: Yes

Substrate in Culvert?: Unknown

What proportion has backwater?: 25%

Culvert Slope: level and uniform

Outlet Gap: None

Embedded?: No

Pool Depth: None

Scour pool apparent?: No

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: lots of slash in tributary channel. Blockage caused by organic debris.

Crossing ID: WC_0002

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180508-162612.jpg
Description: Downstream



Photo No.: Photos-20180508-162630.jpg
Description: Outlet



Photo No.: Photos-20180508-162642.jpg
Description: Erosion



Photo No.: Photos-20180508-162720.jpg
Description: Upstream




Photo No.: Photos-20180508-162755.jpg
Description: Inlet



Photo No.: Photos-20180508-162828.jpg
Description: Blockage

Crossing ID: WC_0002

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 07, 2018

Watercourse Name: Little Egg

GRS Co-ordinates:

UTM: 12 | **Easting:** 321,443 | **Northing:** 5,978,042

Stream Classification: Non-Fluvial, small permanent

Bankfull Width: 4m (Estimated to Nearest Metre)

Crossing Type: Culvert - Multiple

Culvert(s) Diameter: 1) 1.15 m
2) 1.73 m

Erosion at Site: No

Structural Problems: Yes, damaged and undersized culvert

Greater than 10% of the culvert diameter blocked by debris?: Yes

Substrate in Culvert?: Yes **Substrate Type:** gravel and cement

For what length of culvert?: unknown

What proportion has backwater?: 25%

Culvert Slope: level and uniform

Outlet Gap: none

Embedded?: No

Pool Depth: 0.39 m

Scour pool apparent?: No

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Culvert 1 (N/S along road): 10% blockage by fence post in water collecting veg, outlet pool 0.53m. Culvert 2 (diagonal): cement bottom at outlet, pool at outlet is formed by cement 0.25m. Damage on this culvert. Very close to gravel road. Average outlet pool depth: 0.39m.

Crossing ID: WC_0018



Photo No.: Photos-20180507-162505.jpg
Description: Culvert 2 - Downstream



Photo No.: Photos-20180507-162522.jpg
Description: Culvert 2 - Outlet



Photo No.: Photos-20180507-162552.jpg
Description: Culvert 2 - Cement bottom with pool



Photo No.: Photos-20180507-162701.jpg
Description: Culvert 1 - Downstream



Photo No.: Photos-20180507-162718.jpg
Description: Culvert 1 - Outlet



Photo No.: Photos-20180507-162809.jpg
Description: Culvert 1 and 2 - Upstream

Crossing ID: WC_0018

NSW Sturgeon River Watercourse Assessment



Photo No.: Photos-20180507-162857.jpg
Description: Culvert 1 - Inlet



Photo No.: Photos-20180507-162914.jpg
Description: Culvert 2 - Inlet



Photo No.: Photos-20180507-162947.jpg
Description: Culvert 1 - Blockage In

Crossing ID: WC_0018

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 04, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 12 | **Easting:** 348,794 | **Northing:** 5,969,157

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 18m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Potential **Erosion Location (Inlet or Outlet):** Outlet

Erosion Source: Other - cattle pen

Erosion Extent: Medium **Total Erosion Area:** 100 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 25 m

Deck Width (Number of Lanes): 1

Decking Material: Other - Steel with timber planks

Decking Pattern: Open

Curb Type: None - There is no curb, or the curb pattern has openings

Road Surface Material: Gravel

Abutment Type: Treated Lumber

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Structural Problems: None

Bridge Signs: Yes, sign is present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Cattle access created erosion along riparian area of river. This area is now non vegetated.

Crossing ID: WC_0075



Photo No.: Photos-20180504-163047.jpg
Description: Deck



Photo No.: Photos-20180504-163114.jpg
Description: Downstream



Photo No.: Photos-20180504-163203.jpg
Description: Upstream



Photo No.: Photos-20180504-164218.jpg
Description: Inlet



Photo No.: Photos-20180504-164511.jpg
Description: Outlet



Photo No.: Photos-20180504-164539.jpg
Description: Erosion (Cattle Pen)

Crossing ID: WC_0075

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 04, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 12 | **Easting:** 347,232 | **Northing:** 5,968,217

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 17m (Estimated to Nearest Metre)

Crossing Type: Other - concrete culvert - outlet

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Outlet

Erosion Source: Fill Slope

Erosion Extent: Low **Total Erosion Area:** 400 m²

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 100%

Culvert Slope: level and uniform

Outlet Gap: none **Embedded?:** Unknown

Pool Depth: none **Scour pool apparent?:** No

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Fill slope erosion is high.

Crossing ID: WC_0078

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180504-170033.jpg
Description: Outlet



Photo No.: Photos-20180504-170257.jpg
Description: Downstream



Photo No.: Photos-20180504-170322.jpg
Description: Erosion

Crossing ID: WC_0078

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 04, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 12 | **Easting:** 347,216 | **Northing:** 5,968,207

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 12m (Estimated to Nearest Metre)

Crossing Type: Other - concrete culvert

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Inlet

Erosion Source: Bank Slump, Fill Slope

Erosion Extent: Low **Total Erosion Area:** 15 m²

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 100%

Culvert Slope: Level and uniform

Outlet Gap: none

Embedded?: Unknown

Pool Depth: none

Scour pool apparent?: none

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments:

Crossing ID: WC_0083

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180504-171438.jpg
Description: Inlet



Photo No.: Photos-20180504-171521.jpg
Description: Upstream



Photo No.: Photos-20180504-171604.jpg
Description: Erosion Bank Slump

Crossing ID: WC_0083

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 08, 2018

Watercourse Name: Riviere Qui Barre

GPS Co-ordinates:

UTM: 12 | **Easting:** 306,503 | **Northing:** 5,971,467

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 5m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Active **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Ditch Gully, Other (cattle access)

Erosion Extent: High **Total Erosion Area:** 8 m²

Most Common Bridge Substructure Material: Concrete

Total Deck Length: 6 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: None

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: No- in good condition but materials eroding from the side

Armour: None

Opening Blockage: 0%

Cause of blockage: Debris

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: bridge is at its capacity. Structural integrity is hard to determine. There is a fence in the water. Biggest concern is the unrestricted access that cattle have to the water. The channel banks are eroded and flattened out cattle prints. Erosional evidence of soil creating a peninsula in water.

Crossing ID: WC_0082



Photo No.: Photos-20180508-184817.jpg
Description: Inlet



Photo No.: Photos-20180508-184838.jpg
Description: Upstream



Photo No.: Photos-20180508-184851.jpg
Description: Erosion Ditch Slumping



Photo No.: Photos-20180508-184908.jpg
Description: Deck



Photo No.: Photos-20180508-184926.jpg
Description: Downstream



Photo No.: Photos-20180508-184958.jpg
Description: Outlet

Crossing ID: WC_0082

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180508-185041.jpg
Description: Erosion - Cattle Access

Crossing ID: WC_0082

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 07, 2018

Watercourse Name: Little Egg Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 327,044 | **Northing:** 5,968,112

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 8m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single **Culvert(s) Diameter:** 2.29m

Erosion at Site: No

Structural Problems: Yes, undersized culvert

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 75%

Culvert Slope: Level and Uniform

Outlet Gap: None

Embedded?: No

Pool Depth: None

Scour pool apparent?: No

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Inlet bankfull width > culvert inlet, thereby creating back pooling.

Crossing ID: WC_0091



Photo No.: Photos-20180507-181535.jpg
Description: Downstream



Photo No.: Photos-20180507-181553.jpg
Description: Outlet



Photo No.: Photos-20180507-181637.jpg
Description: Upstream



Photo No.: Photos-20180507-181730.jpg
Description: Inlet

Crossing ID: WC_0091

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 08, 2018

Watercourse Name: Riviere Qui Barre

GPS Co-ordinates:

UTM: 12 | **Easting:** 306,065 | **Northing:** 5,968,897

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 7m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Potential **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Bank Slump, Other (wing wall collapsing)

Erosion Extent: Low **Total Erosion Area:** 2 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 5 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: No, missing abutment

Wingwall Functioning?: No, damage to wingwall

Armour: None

Structural Problems: Damaged Guardrail, Other - large spaces between pavement deck slates, missing abutment piling, wingwall not secure

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Damaged, sign is either down or needs to be replaced

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Capacity of bridge has been reached and difficult to determine integrity.

Crossing ID: WC_0110

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180508-190411.jpg
Description: Outlet



Photo No.: Photos-20180508-190423.jpg
Description: Downstream



Photo No.: Photos-20180508-190503.jpg
Description: Deck



Photo No.: Photos-20180508-190519.jpg
Description: Upstream



Photo No.: Photos-20180508-190540.jpg
Description: Inlet



Photo No.: Photos-20180508-190608.jpg
Description: Wing Wall Damage

Crossing ID: WC_0110

NSW Sturgeon River Watercourse Assessment



Photo No.: Photos-20180508-190647.jpg
Description: abutment Wall Damage

Crossing ID: WC_0110

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 04, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 12 | **Easting:** 344,138 | **Northing:** 5,965,865

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 15m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Fill Slope

Erosion Extent: medium **Total Erosion Area:** 10 m²

Most Common Bridge Substructure Material: Concrete

Total Deck Length: 18 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Concrete Blocks

Abutment Functioning?: No - falling apart and/or materials eroding from underneath

Wingwall Functioning?: None

Armour: Other - concrete blocks with some large bouldered riprap

Opening Blockage: 0%

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: No, sign is not present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: concrete armour blocks are only on one side. Very large boulders used for rip rap.

Crossing ID: WC_0111

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180504-175134.jpg
Description: Deck



Photo No.: Photos-20180504-175857.jpg
Description: Downstream



Photo No.: Photos-20180504-175921.jpg
Description: Outlet



Photo No.: Photos-20180504-180042.jpg
Description: Inlet



Photo No.: Photos-20180504-180118.jpg
Description: Upstream



Photo No.: Photos-20180504-180131.jpg
Description: Erosion

Crossing ID: WC_0111

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180504-180156.jpg
Description: Erosion

Crossing ID: WC_0111

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 07, 2018

Watercourse Name: Little Egg Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 327,492 | **Northing:** 5,965,561

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 10m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 4 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: No - falling apart and/or materials eroding from underneath

Armour: None

Opening Blockage: 0%

Structural Problems: V -Vegetation protruding

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Bridge is as wide as stream. Stream is in contact with treated lumber abutments and treated lumber wingwalls.

Crossing ID: WC_0119



Photo No.: Photos-20180507-191723.jpg
Description: Upstream



Photo No.: Photos-20180507-191740.jpg
Description: Inlet



Photo No.: Photos-20180507-191846.jpg
Description: Downstream



Photo No.: Photos-20180507-191928.jpg
Description: Outlet & Wingwall condition-materials falling



Photo No.: Photos-20180507-192347.jpg
Description: City Drainage

Crossing ID: WC_0119

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 07, 2018

Watercourse Name: Little Egg Creek

GPS Coordinates:

UTM: 12 | **Easting:** 329,119 | **Northing:** 5,965,205

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 14m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Culvert diameter: 1.75m

Erosion at Site: Yes

Erosion Location (Inlet or Outlet): Inlet

Erosion Source: Bank Slump **Total Erosion Area:** 20 m²

Erosion Extent: Low

Structural Problems: Yes, undersized culvert

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: unknown

Substrate Type: unknown

For what length of culvert?: unknown

What proportion has backwater?: 75%

Culvert Slope: Level and Uniform

Embedded?: no

Outlet Gap: none

Scour pool apparent?: No

Pool Depth: none

Other: Inlet bankfull width > culvert inlet.

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Erosion is biggest concern

Crossing ID: WC_0130

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180507-193305.jpg
Description: Downstream



Photo No.: Photos-20180507-193318.jpg
Description: Outlet



Photo No.: Photos-20180507-193555.jpg
Description: Upstream



Photo No.: Photos-20180507-193625.jpg
Description: Inlet

Crossing ID: WC_0130

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 04, 2018

Watercourse Name: Sturgeon River

GPS Coordinates:

UTM: 12 | **Easting:** 353,533 | **Northing:** 5,962,137

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 14m (Measured)

Crossing Type: Bridge - Permanent

Erosion at Site: Active **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Ditch Gully, Bank Slump

Erosion Extent: High **Total Erosion Area:** 10 m²

Most Common Bridge Substructure Material: Concrete

Total Deck Length: 20 m

Deck Width (Number of Lanes): 2

Decking Material: Other - pavement

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Concrete Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: Other - concrete

Opening Blockage: 0%

Structural Problems: Yes, DG

Bridge Signs: Yes, sign is present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Heavy Erosion

Crossing ID: WC_0132



Photo No.: Photos-20180504-152758.jpg
Description: Downstream



Photo No.: Photos-20180504-152905.jpg
Description: Outlet



Photo No.: Photos-20180504-153124.jpg
Description: Erosion



Photo No.: Photos-20180504-153148.jpg
Description: Erosion



Photo No.: Photos-20180504-153310.jpg
Description: Upstream



Photo No.: Photos-20180504-153340.jpg
Description: Inlet

Crossing ID: WC_0132

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 07, 2018

Watercourse Name: Little Egg Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 329,749 | **Northing:** 5,964,774

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 12m (Estimated to Nearest Metre)

Crossing Type: Culvert - Multiple

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Inlet

Erosion Source: Bank Slump

Erosion Extent: High **Total Erosion Area:** 5 m²

Culvert(s) Diameter: 1) 4.6 m
2) 4.6 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: No **Substrate Type:** None

For what length of culvert?: None

What proportion has backwater?: 100%

Culvert Slope: Level and Uniform

Embedded?: No

Outlet Gap: none

Pool Depth: none

Scour pool apparent?: No

Structural Problems: No

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: beaver footprints in mud.

Crossing ID: WC_0140



Photo No.: Photos-20180507-194508.jpg
Description: Bank slump in culvert



Photo No.: Photos-20180507-194845.jpg
Description: Upstream



Photo No.: Photos-20180507-194910.jpg
Description: Inlet



Photo No.: Photos-20180507-194934.jpg
Description: Sediment in



Photo No.: Photos-20180507-195113.jpg
Description: Downstream



Photo No.: Photos-20180507-195146.jpg
Description: Outlet

Crossing ID: WC_0140

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 07, 2018

Watercourse Name: Little Egg Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 330,726 | **Northing:** 5,964,712

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 10m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 7 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - but one piling (middle south) is pulling away from abutment wall

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 25% **Cause of Blockage:** Gabions placed in stream

Structural Problems: one piling (middle south) is pulling away from abutment wall

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Gabions located approximately 10m upstream of bridge is causing the stream to bottleneck creating higher velocity of water and blockage concerns for fish to travel upstream. The middle log piling along the southern abutment wall is pulling away from the wall.

Crossing ID: WC_0141



Photo No.: Photos-20180507-200512.jpg
Description: Upstream



Photo No.: Photos-20180507-200523.jpg
Description: Gabion



Photo No.: Photos-20180507-200601.jpg
Description: Gabion



Photo No.: Photos-20180507-200610.jpg
Description: Inlet



Photo No.: Photos-20180507-200632.jpg
Description: Downstream



Photo No.: Photos-20180507-200715.jpg
Description: Outlet

Crossing ID: WC_0141

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 04, 2018

Watercourse Name: Sturgeon River

UTM: 12 | **Easting:** 340,450 | **Northing:** 5,961,909

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 18m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Fill Slope

Erosion Extent: Low **Total Erosion Area:** 20 m²

Most Common Bridge Substructure Material: Concrete

Total Deck Length: 21 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Concrete Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: No Armour to mitigate fill slope erosion.

Crossing ID: WC_0165



Photo No.: Photos-20180504-182125.jpg
Description: Deck



Photo No.: Photos-20180504-182803.jpg
Description: Upstream



Photo No.: Photos-20180504-182820.jpg
Description: Inlet




Photo No.: Photos-20180504-182858.jpg
Description: Downstream



Photo No.: Photos-20180504-182950.jpg
Description: Outlet

Crossing ID: WC_0165

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 07, 2018

Watercourse Name: Carrot Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 326,176 | **Northing:** 5,961,665

Stream Classification: Fluvial (Intermittent)

Bankfull Width: 5m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Erosion at Site: Potential **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Ditch Gully

Erosion Extent: Low **Total Erosion Area:** 10 m²

Culvert(s) Diameter: 0.9 m

Greater than 10% of the culvert diameter blocked by debris?: No

Structural Problems: None

Substrate in Culvert?: Yes **Substrate Type:** Gravel, Sand, Other

For what length of culvert?: 25%

What proportion has backwater?: 0%

Culvert Slope: Level and Uniform

Outlet Gap: None

Embedded?: No

Pool Depth: None

Scour pool apparent?: No

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Culvert directly south of South Glenn sub development. Man made storm water pond directly north through a fence. 2 other points located within housing development wc_0181 and wc_0181. There was no water and houses in area. Fault on old data. Area is headwaters for Carrot Creek. Channel has been dried up.

Crossing ID: WC_0184



Photo No.: Photos-20180507-211244.jpg
Description: Upstream



Photo No.: Photos-20180507-211324.jpg
Description: Inlet



Photo No.: Photos-20180507-211348.jpg
Description: Outlet



Photo No.: Photos-20180507-211359.jpg
Description: Downstream



Photo No.: Photos-20180507-211515.jpg
Description: 32m from culvert is defined channel

Crossing ID: WC_0184

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 08, 2018

Watercourse Name: Riviere Qui Barre

GPS Co-ordinates:

UTM: 12 | **Easting:** 308,607 | **Northing:** 5,962,319

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 6m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 11 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: No - not good condition and but no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: Riprap

Opening Blockage: 10%

Cause of blockage: Debris

Structural Problems: Yes, abutments are rotting

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: The abutments are looking like they need to be replaced. Looks like some work has been done but nothing that's meant to last for a long time. Since the abutments pilings are in the water, there are logs starting to collect creating blockages.

Crossing ID: WC_0199



Photo No.: Photos-20180508-201729.jpg
Description: Inlet



Photo No.: Photos-20180508-201808.jpg
Description: Upstream



Photo No.: Photos-20180508-201834.jpg
Description: Deck



Photo No.: Photos-20180508-201846.jpg
Description: Downstream



Photo No.: Photos-20180508-201911.jpg
Description: Outlet

Crossing ID: WC_0199

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 14, 2018

Watercourse Name: Toad Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 684,519 | **Northing:** 5,961,499

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 10m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 7 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - but stream is in contact

Armour: None

Opening Blockage: 0%

Structural Problems: Yes, wingwall function

Other: Wetted width flooding slightly past wingwall, potential safety issues.

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Wetted width is wider than bridge and is past the wingwalls. Deceased beaver near bridge, no visible dam or lodge.

Crossing ID: WC_0201



Photo No.: Photos-20180514-181259.jpg
Description: Upstream



Photo No.: Photos-20180514-181339.jpg
Description: Inlet



Photo No.: Photos-20180514-181412.jpg
Description: Deck



Photo No.: Photos-20180514-181439.jpg
Description: Downstream



Photo No.: Photos-20180514-181537.jpg
Description: Outlet

Crossing ID: WC_0201

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 04, 2018

Watercourse Name: Little Egg Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 333,618 | **Northing:** 5,958,308

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 1.5m (Measured)

Crossing Type: Culvert - Single

Culvert(s) Diameter: 3m

Erosion at Site: No

Structural Problems: None

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** Unknown

For what length of culvert?: Unknown

What proportion has backwater?: 100%

Culvert Slope: Level and uniform

Outlet Gap: None

Embedded?: No

Pool Depth: None

Scour pool apparent?: None

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments:

Fish passage has some concerns upstream due to the steep grade caused by instream rip rap, which creates turbulence and difficulties for weak swimmers. Maintenance is recommended to remove the instream rip rap to the channel bank.

Crossing ID: WC_0218

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180504-203044.jpg
Description: Upstream



Photo No.: Photos-20180504-203131.jpg
Description: Inlet



Photo No.: Photos-20180504-203452.jpg
Description: Downstream



Photo No.: Photos-20180504-203645.jpg
Description: Outlet

Crossing ID: WC_0218

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 04, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 12 | Easting: 337,417 | Northing: 5,958,021

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 15m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Fill Slope

Erosion Extent: High **Total Erosion Area:** 8 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 16 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Damaged, sign is either down or needs to be replaced

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: No armour present. High erosion on west fill slope. Abutment wall piling appearing. No materials eroding from under abutment wall but fill slope is eroding into stream. Abutment pilings in water with treated lumber walls are in stream.

Crossing ID: WC_0226



Photo No.: Photos-20180504-192500.jpg
Description: Downstream



Photo No.: Photos-20180504-192539.jpg
Description: Deck



Photo No.: Photos-20180504-192613.jpg
Description: Outlet



Photo No.: Photos-20180504-192735.jpg
Description: Inlet



Photo No.: Photos-20180504-192759.jpg
Description: Upstream



Photo No.: Photos-20180504-193350.jpg
Description: Erosion West

Crossing ID: WC_0226

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 18, 2018

Watercourse Name: Carrot Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 325,748 | **Northing:** 5,958,431

Stream Classification: Fluvial (Permanent - Small)

Bankful Width: 4m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Road Surface, Bridge Deck

Erosion Extent: High **Total Erosion Area:** 4 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 4 m

Deck Width (Number of Lanes): 1

Decking Material: Wood

Decking Pattern: Open

Curb Type: None - There is no curb, or the curb pattern has openings

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Abutment pilings and walls are in contact with the stream. No armour present. Road surface is collecting in piling instream. On the north side of the bridge, a small drainage ditch has been dug to channelize ditch water. There is no armour to protect stream from earth movement from dug channel.

Crossing ID: WC_0231

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180518-151328.jpg
Description: Deck



Photo No.: Photos-20180518-151350.jpg
Description: Upstream



Photo No.: Photos-20180518-151411.jpg
Description: Downstream



Photo No.: Photos-20180518-151506.jpg
Description: Outlet



Photo No.: Photos-20180518-151547.jpg
Description: Sediment buildup



Photo No.: Photos-20180518-151658.jpg
Description: Ditch drainage

Crossing ID: WC_0231

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 18, 2018

Watercourse Name: Carrot Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 325,544 | **Northing:** 5,958,025

Stream Classification: Ephemeral

Bankfull Width: 1m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Erosion at Site: No

Structural Problems: Others- culvert not utilized for stream connectivity.

Culvert(s) Diameter: 1) 0.5 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 0%

Culvert Slope: Level and Uniform

Outlet Gap: none

Embedded?: No

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Unsure if this is a true Carrot Creek crossing. This culvert is on the west side of highway 2 between the southbound lane and a side road. Carrot Creek ran along the side of the northbound lane. This could of been the historical route. Hard to determine is this is true. It is believed this culvert is utilized for minimal storm water passage under the road. No water at time of assessment. Last years cattails still standing, no signs of regeneration. Ground is soft. Couple of cement slabs on top of culvert. Some fish passage concerns due to the lack of connectivity of stream to culvert. Unable to safely view the culverts inlet, which was between northbound and southbound lanes of Highway 2.

Crossing ID: WC_0245

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180518-153036.jpg
Description: Downstream



Photo No.: Photos-20180518-153051.jpg
Description: Outlet



Photo No.: Photos-20180518-153329.jpg
Description: Outlet

Crossing ID: WC_0245

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 08, 2018

Watercourse Name: Riviere Qui Barre

GPS Co-ordinates:

UTM: 12 | **Easting:** 310,688 | **Northing:** 5,958,998

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 5m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Concrete

Total Deck Length: 12 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: None

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: Riprap

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Damaged, sign is either down or needs to be replaced

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: 1 of 4 grader markers are present

Crossing ID: WC_0256



Photo No.: Photos-20180508-205510.jpg
Description: Upstream



Photo No.: Photos-20180508-205555.jpg
Description: Inlet



Photo No.: Photos-20180508-205629.jpg
Description: Deck



Photo No.: Photos-20180508-205700.jpg
Description: Outlet



Photo No.: Photos-20180508-205734.jpg
Description: Downstream

Crossing ID: WC_0256

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 08, 2018

Watercourse Name: Riviere Qui Barre

GPS Co-ordinates:

UTM: 12 | **Easting:** 310,820 | **Northing:** 5,957,722

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 8m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 7 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: None, no pilings only timber planks on walls

Abutment Functioning?: Yes

Wingwall Functioning?: Yes, but vegetation is moving around the wingwall

Armour: None

Opening Blockage: 0%

Structural Problems: Yes, wingwalls are not containing vegetation and the abutment walls are in contact with the stream, leaving integrity unknown

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Larger wingwalls present, however stream angles to flow under bridge. The south eastern wingwall will see the most pressure from this. Vegetation is encroaching around this wall.

Crossing ID: WC_0259



Photo No.: Photos-20180508-210709.jpg
Description: Outlet



Photo No.: Photos-20180508-210730.jpg
Description: Deck



Photo No.: Photos-20180508-210757.jpg
Description: Downstream




Photo No.: Photos-20180508-210817.jpg
Description: Upstream



Photo No.: Photos-20180508-210839.jpg
Description: Inlet

Crossing ID: WC_0259

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 14, 2018

Watercourse Name: Toad Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 687,862 | **Northing:** 5,959,626

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 6m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Erosion at Site: No

Structural Problems: Yes, undersized culvert.

Culvert(s) Diameter: 1) 1.9 m

Greater than 10% of the culvert diameter blocked by debris?: Yes

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: <25%

Culvert Slope: Level and Uniform

Outlet Gap: 0.1 m

Embedded?: no

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: Serious Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: There is a beaver dam blocking 95% of water at the inlet. Large back pool formed. Pool is stilling 0.5 meters higher than culvert. Serious fish passage concerns due to the lack of water downstream and through the culvert. Risk of flooding downstream and along road if the dam breaks.

Crossing ID: WC_0260

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180514-184735.jpg
Description: Upstream



Photo No.: Photos-20180514-184820.jpg
Description: Inlet



Photo No.: Photos-20180514-184947.jpg
Description: Beaver dam



Photo No.: Photos-20180514-185019.jpg
Description: Downstream



Photo No.: Photos-20180514-185103.jpg
Description: Outlet

Crossing ID: WC_0260

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 14, 2018

Watercourse Name: Toad Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 690,534 | **Northing:** 5,958,992

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 5m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 9 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Steel Piling

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: No - falling apart

Armour: None

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: Yes, wingwalls are falling apart and allowing vegetation to protrude

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: steel abutments redone, with lumber behind for abutment walls. Wingwalls have vegetation wrapping around. Fence in stream could create blockage issues in future. Capacity of bridge has been reached and difficult to determine integrity.

Crossing ID: WC_0265

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180514-191537.jpg
Description: Downstream



Photo No.: Photos-20180514-191550.jpg
Description: Upstream



Photo No.: Photos-20180514-191655.jpg
Description: Inlet



Photo No.: Photos-20180514-191736.jpg
Description: Deck



Photo No.: Photos-20180514-191757.jpg
Description: Outlet

Crossing ID: WC_0265

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 14, 2018

Watercourse Name: Toad Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 690,531 | **Northing:** 5,958,888

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 5m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Culvert(s) Diameter: 1) 0.5 m

Erosion at Site: No

Structural Problems: Yes, culvert is undersized.

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 100%

Culvert Slope: Level and Uniform

Outlet Gap: none

Embedded?: unknown

Pool Depth: none

Scour pool apparent?: unknown

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Low laying area with flooding, riparian areas and large grassy wetlands. Road where culvert was, very low. Road is probably at risk for flooding. Could not find the outlet of culvert, completely submerged. Trumpeter swans noted utilizing habitat. GPS location was incorrect, actually location was 25m south.

Crossing ID: WC_0276

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180514-193339.jpg
Description: Upstream



Photo No.: Photos-20180514-193351.jpg
Description: Inlet



Photo No.: Photos-20180514-193407.jpg
Description: Outlet / Downstream



Photo No.: Photos-20180514-193507.jpg
Description: Swans

Crossing ID: WC_0276

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 14, 2018

Watercourse Name: Toad Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 690,554 | **Northing:** 5,958,824

Stream Classification: Non-Fluvial

Bankfull Width: 1m (Measured)

Crossing Type: Culvert - Single

Erosion at Site: No

Structural Problems: None

Culvert(s) Diameter: 1) 0.5 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 0%

Culvert Slope: Level and Uniform

Outlet Gap: none

Embedded?: No

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: Serious Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Greater area resembles a flood plain. Large wetland area near by. Crossing is 100m southeast of GPS location initially provided. Has the area changed or directly of flow changed?

Crossing ID: WC_0278



Photo No.: Photos-20180514-192807.jpg
Description: Upstream



Photo No.: Photos-20180514-192827.jpg
Description: Inlet



Photo No.: Photos-20180514-192850.jpg
Description: Downstream



Photo No.: Photos-20180514-192901.jpg
Description: Outlet

Crossing ID: WC_0278

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 14, 2018

Watercourse Name: Toad Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 690,983 | **Northing:** 5,957,546

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 6m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Fill Slope

Erosion Extent: Low **Total Erosion Area:** 16 m²

Most Common Bridge Substructure Material: Steel

Total Deck Length: 17 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Non vegetated fill slopes. Erosional concern.

Crossing ID: WC_0307



Photo No.: Photos-20180514-195247.jpg
Description: Upstream



Photo No.: Photos-20180514-195302.jpg
Description: Inlet



Photo No.: Photos-20180514-195523.jpg
Description: Erosion



Photo No.: Photos-20180514-195542.jpg
Description: Downstream



Photo No.: Photos-20180514-195555.jpg
Description: Outlet

Crossing ID: WC_0307

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 11, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 679,784 | **Northing:** 5,957,391

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 8m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Potential **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Fill Slope

Erosion Extent: Low **Total Erosion Area:** 6 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 12 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: Yes, northern abutment wall looks like its angling inwards

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Damaged, sign is either down or needs to be replaced

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Erosional concerns with fill slope. Abutment wall on the north side looks like its angling in.

Crossing ID: WC_0309



Photo No.: Photos-20180511-192209.jpg
Description: Deck



Photo No.: Photos-20180511-192239.jpg
Description: Upstream



Photo No.: Photos-20180511-192300.jpg
Description: Downstream




Photo No.: Photos-20180511-192346.jpg
Description: Outlet



Photo No.: Photos-20180511-192514.jpg
Description: Inlet

Crossing ID: WC_0309

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 18, 2018

Watercourse Name: Carrot Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 324,201 | **Northing:** 5,955,245

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 4m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Erosion at Site: No

Structural Problems: None

Culvert(s) Diameter: 1) 1.6 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 25%

Culvert Slope: Level and Uniform

Outlet Gap: none

Embedded?: no

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Smaller culvert is converging to inlet of Carrot Creek and has an outlet gap of 0.45m, however it has no water at time. Second smaller culvert is ditch drainage from east side of road which collects runoff from manicured lawn and drains into Carrot Creek. Area near water smells.

Crossing ID: WC_0315



Photo No.: Photos-20180518-163313.jpg
Description: Upstream



Photo No.: Photos-20180518-163336.jpg
Description: Inlet - larger culvert



Photo No.: Photos-20180518-163415.jpg
Description: Outlet smaller culvert is ditch drainage



Photo No.: Photos-20180518-163618.jpg
Description: Smaller culvert inlet



Photo No.: Photos-20180518-163641.jpg
Description: Smaller culvert Upstream



Photo No.: Photos-20180518-163923.jpg
Description: Outlet

Crossing ID: WC_0315

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180518-163943.jpg
Description: Downstream



Photo No.: Photos-20180518-164044.jpg
Description: Drainage ditch culvert 10m from outlet which flows from a manicured lawn

Crossing ID: WC_0315

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 07, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 12 | **Easting:** 331,511 | **Northing:** 5,954,935

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 18m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Fill Slope

Erosion Extent: Low **Total Erosion Area:** 4 m²

Most Common Bridge Substructure Material: Steel

Total Deck Length: 22 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Steel Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: Yes, Damaged guardrail

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Damaged, sign is either down or needs to be replaced

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Wingwall on east outlet is exposed from erosion. Fill slope erosion due to no armour.

Crossing ID: WC_0316

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180507-213649.jpg
Description: Downstream



Photo No.: Photos-20180507-213705.jpg
Description: Outlet



Photo No.: Photos-20180507-213746.jpg
Description: Inlet



Photo No.: Photos-20180507-213756.jpg
Description: Upstream



Photo No.: Photos-20180507-213848.jpg
Description: Erosion

Crossing ID: WC_0316

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 11, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 684,702 | **Northing:** 5,956,967

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 9m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 12 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Other - log piling with 3 steel beams reinforcing

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: <10%

Cause of blockage: Beaver

Structural Problems: yes, other- curb is crumbling

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Curb on southwestern side is starting to crumble. There is an old beaver dam present at inlet. It has partially broke. Creates fish passage concerns.

Crossing ID: WC_0339



Photo No.: Photos-20180511-202414.jpg
Description: Deck



Photo No.: Photos-20180511-202503.jpg
Description: Inlet



Photo No.: Photos-20180511-202526.jpg
Description: Upstream



Photo No.: Photos-20180511-202557.jpg
Description: Downstream



Photo No.: Photos-20180511-202633.jpg
Description: Outlet




Photo No.: Photos-20180511-203039.jpg
Description: Beaver Dam

Crossing ID: WC_0339

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 11, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 666,259 | **Northing:** 5,956,365

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 40m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both **Erosion Extent:** Low

Erosion Source: Bank Slump, Ditch Gully **Total Erosion Area:** 6 m²

Most Common Bridge Substructure Material: Concrete

Total Deck Length: 25 m

Deck Width (Number of Lanes): 1

Decking Material: Wood

Decking Pattern: Open

Curb Type: None - There is no curb, or the curb pattern has openings

Road Surface Material: Other - pavement

Abutment Type: Concrete Blocks

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: No, slats within walls allowing materials to fall through

Armour: Other - cement slabs

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: None

Bridge Signs: Yes, sign is present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Area around bridge seems to be well used (paths down to rivers edge, chairs, garbage). Bank slumping occurring near edges as well as road material gathering off road. Water level is at concrete abutment height, unable to determine if materials could be eroding from under (lower water levels could show this).

Crossing ID: WC_0347





Photo No.: Photos-20180511-171727.jpg
Description: Upstream



Photo No.: Photos-20180511-171738.jpg
Description: Inlet



Photo No.: Photos-20180511-171930.jpg
Description: Erosion under abutment



Photo No.: Photos-20180511-171957.jpg
Description: Downstream



Photo No.: Photos-20180511-172007.jpg
Description: Outlet



Photo No.: Photos-20180511-172039.jpg
Description: Slumping

Crossing ID: WC_0347

NSW Sturgeon River Watercourse Assessment



Photo No.: Photos-20180511-172301.jpg
Description: Ditch gully / road materials



Photo No.: Photos-20180511-172359.jpg
Description: Deck

Crossing ID: WC_0347

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 11, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 688,152 | **Northing:** 5,955,787

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 6m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Fill Slope, Bank Slump **Erosion Extent:** High **Total Erosion Area:** 32 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 22 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition but materials moving around walls

Armour: None

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Material moving around wingwall. Abutments are in stream with lumber surrounding it and against fill slope. Water can get between fill slope and abutment lumber wall causing fill slope erosion to occur.

Crossing ID: WC_0353



Photo No.: Photos-20180511-210337.jpg
Description: Downstream



Photo No.: Photos-20180511-210354.jpg
Description: Outlet



Photo No.: Photos-20180511-210530.jpg
Description: Inlet



Photo No.: Photos-20180511-210546.jpg
Description: Upstream



Photo No.: Photos-20180511-210602.jpg
Description: Old beaver dam

Crossing ID: WC_0353

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 11, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 689,647 | **Northing:** 5,956,031

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 6m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 16 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: Yes, damaged guardrail

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Low

Comments: Bridge is at capacity for water level, hard to determine integrity of structure.

Noted to find 2 dead adult foxes near waters edge

Crossing ID: WC_0357



Photo No.: Photos-20180511-211227.jpg
Description: Downstream



Photo No.: Photos-20180511-211255.jpg
Description: Upstream



Photo No.: Photos-20180511-211314.jpg
Description: Deck



Photo No.: Photos-20180511-211351.jpg
Description: Inlet



Photo No.: Photos-20180511-211457.jpg
Description: Outlet

Crossing ID: WC_0357

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 16, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 12 | **Easting:** 317,514 | **Northing:** 5,948,995

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 6m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Bank Slump, Fill Slope

Erosion Extent: High **Total Erosion Area:** 8 m²

Most Common Bridge Substructure Material: Steel

Total Deck Length: 25 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Steel Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: Other - abutment steel wall on one side

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: No

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Damaged, sign is either down or needs to be replaced

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Heavy slumping into river on fill slope on east side of river. No steel abutment wall on the erosion side like the other.

Train bridge directly downstream.

Crossing ID: WC_0530



Photo No.: Photos-20180516-210322.jpg
Description: Outlet



Photo No.: Photos-20180516-210445.jpg
Description: Downstream



Photo No.: Photos-20180516-210502.jpg
Description: Erosion



Photo No.: Photos-20180516-210557.jpg
Description: Inlet



Photo No.: Photos-20180516-210609.jpg
Description: Upstream

Crossing ID: WC_0530

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 14, 2018

Watercourse Name: Kilini Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 688,883 | **Northing:** 5,949,217

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 3m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 5 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: No - in good condition but materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: Yes, Abutment wall

Bridge Signs: Yes, sign is present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Materials eroding from under abutment wall. Small beaver dam noted approximately 25m upstream. This crossing is downstream of a gravel wash pit.

Crossing ID: WC_0569



Photo No.: Photos-20180514-165644.jpg
Description: Upstream



Photo No.: Photos-20180514-165709.jpg
Description: Downstream



Photo No.: Photos-20180514-165811.jpg
Description: Inlet



Photo No.: Photos-20180514-165924.jpg
Description: Outlet



Photo No.: Photos-20180514-165952.jpg
Description: Fencing downstream



Photo No.: Photos-20180514-170011.jpg
Description: Under abutment showing

Crossing ID: WC_0569

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180514-170100.jpg
Description: Deck

Crossing ID: WC_0569

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 18, 2018

Watercourse Name: Carrot Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 321,080 | **Northing:** 5,946,530

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 5m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 4 m

Deck Width (Number of Lanes): 1

Decking Material: Wood

Decking Pattern: Open

Curb Type: None - There is no curb, or the curb pattern has openings

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: No materials eroding from underneath

Armour: Riprap

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: None

Bridge Signs: Yes, sign is present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Stream outlet has multiple channels. Some areas with pooled water within a channel, might be caused by old beaver dams. Wingwalls have materials coming around from the side. Road materials in stream bed.

Crossing ID: WC_0577



Photo No.: Photos-20180518-173110.jpg
Description: Deck



Photo No.: Photos-20180518-173213.jpg
Description: Inlet



Photo No.: Photos-20180518-173303.jpg
Description: Upstream



Photo No.: Photos-20180518-173318.jpg
Description: Downstream



Photo No.: Photos-20180518-173355.jpg
Description: Outlet



Photo No.: Photos-20180518-173436.jpg
Description: Old beaver dam?

Crossing ID: WC_0577


NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180518-173452.jpg
Description: Old beaver dam?

Crossing ID: WC_0577

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 18, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 12 | **Easting:** 326,522 | **Northing:** 5,946,318

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 12m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Concrete

Total Deck Length: 30 m

Deck Width (Number of Lanes): 4

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Concrete Blocks

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: Other - concrete blocks/slabs

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: No, sign is not present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Bankfull width and wetted width are very similar. Water level could rise and flood sidewalks and enter stormwater drainage.

Crossing ID: WC_0579



Photo No.: Photos-20180518-200509.jpg
Description: Inlet



Photo No.: Photos-20180518-200539.jpg
Description: Storm water drainage



Photo No.: Photos-20180518-200601.jpg
Description: Upstream




Photo No.: Photos-20180518-200738.jpg
Description: Downstream



Photo No.: Photos-20180518-200751.jpg
Description: Outlet

Crossing ID: WC_0579

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 18, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 12 | **Easting:** 326,313 | **Northing:** 5,946,170

Stream Classification: Fluvial (Permanent - Large)

Bankfull Width: 13m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Concrete

Total Deck Length: 35 m

Deck Width (Number of Lanes): 4

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Concrete Blocks

Abutment Functioning?: Yes - in good condition and no materials eroding from

underneath **Wingwall Functioning?:** Yes - in good condition and no materials eroding from

underneath **Armour:** Other - cement blocks

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: O - cement armour is separated from abutment wall on north side

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: No, sign is not present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: low laying area. River exceeding its banks. Flooding onto sidewalk. There seems to be some separation of the cement abutment wall to the cement armour. There is no grader markers or bridge reflectors.

Crossing ID: WC_0580



Photo No.: Photos-20180518-195437.jpg
Description: Downstream



Photo No.: Photos-20180518-195452.jpg
Description: Outlet



Photo No.: Photos-20180518-195719.jpg
Description: Upstream



Photo No.: Photos-20180518-195736.jpg
Description: Storm water discharge



Photo No.: Photos-20180518-195757.jpg
Description: Inlet



Photo No.: Photos-20180518-195819.jpg
Description: Flooding

Crossing ID: WC_0580

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 18, 2018

Watercourse Name: Carrot Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 321,680 | **Northing:** 5,945,062

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 10m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Steel

Total Deck Length: 5 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Open

Curb Type: None - There is no curb, or the curb pattern has openings

Road Surface Material: Other - pavement

Abutment Type: Steel Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: Riprap

Opening Blockage: 25%

Cause of blockage: Beaver

Structural Problems: None

Bridge Signs: Yes, sign is present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Happy beaver in area. Dam approx 5 meters downstream from bridge at outlet. Looks to be about 10% of water able to get through. Water is back pooling to the point of exceeding its bankfull width around bridge. Water is moving behind wingwalls.

Crossing ID: WC_0598



Photo No.: Photos-20180518-183705.jpg
Description: Deck



Photo No.: Photos-20180518-183853.jpg
Description: Downstream



Photo No.: Photos-20180518-183914.jpg
Description: Outlet



Photo No.: Photos-20180518-183940.jpg
Description: Beaver dam downstream



Photo No.: Photos-20180518-184109.jpg
Description: Upstream



Photo No.: Photos-20180518-184123.jpg
Description: Inlet

Crossing ID: WC_0598

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 16, 2018

Watercourse Name: Atim Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 309,036 | **Northing:** 5,941,805

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 3m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Potential **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Fill Slope

Erosion Extent: Low **Total Erosion Area:** 5 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 6 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Steel Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: Riprap

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: beaver dam leading to fish passage concerns. Ripple up and downstream of bridge caused by larger rocks in water (unsure if natural or not). Rip rap on southside of bridge and not northside.

Crossing ID: WC_0681



Photo No.: Photos-20180516-171528.jpg
Description: Inlet



Photo No.: Photos-20180516-171548.jpg
Description: Beaver dam



Photo No.: Photos-20180516-171708.jpg
Description: Upstream



Photo No.: Photos-20180516-171726.jpg
Description: Downstream



Photo No.: Photos-20180516-171806.jpg
Description: Outlet

Crossing ID: WC_0681

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 16, 2018

Watercourse Name: Atim Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 306,059 | **Northing:** 5,940,239

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 5m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Erosion at Site: No

Culvert(s) Diameter: 1) 3.5 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 75%

Culvert Slope: level and uniform

Outlet Gap: none

Embedded?: Yes

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Beaver dam upstream approx 25m. water has diverted around or a split channel was historically there. Beaver dam down stream is small, approx 30m from culvert

Crossing ID: WC_0725



Photo No.: Photos-20180516-163005.jpg
Description: Upstream



Photo No.: Photos-20180516-163039.jpg
Description: Upstream



Photo No.: Photos-20180516-163144.jpg
Description: Inlet



Photo No.: Photos-20180516-163212.jpg
Description: Beaver dam upstream



Photo No.: Photos-20180516-163332.jpg
Description: Downstream south



Photo No.: Photos-20180516-163347.jpg
Description: Downstream north

Crossing ID: WC_0725

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180516-163410.jpg
Description: Downstream from culvert



Photo No.: Photos-20180516-163501.jpg
Description: Outlet



Photo No.: Photos-20180516-163530.jpg
Description: Beaver dam downstreams

Crossing ID: WC_0725

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 09, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 641,626 | **Northing:** 5,940,192

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 5m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 20 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: Riprap

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Deeper stream channel (>1 meter) directly up and downstream of bridge. Directly under the bridge only had a depth of water to be 0.1-0.2 meters with small boulders assumed to be rip rap placed there for bridge erosion control. White suckers were present at the time of assessment and were demonstrating difficulties trying to pass the rip rap. The stream over the rip rap was rapid and moving quickly. Alternatively, the area provides suitable substrate for laying eggs and could be spawning habitat. Recommend further investigation prior to commencing any instream activities.

Crossing ID: WC_0758



Photo No.: Photos-20180509-194900.jpg
Description: Deck



Photo No.: Photos-20180509-195108.jpg
Description: Downstream



Photo No.: Photos-20180509-195408.jpg
Description: White suckers in Ripple



Photo No.: Photos-20180509-201037.jpg
Description: Upstream



Photo No.: Photos-20180509-201101.jpg
Description: Inlet



Photo No.: Photos-20180509-202243.jpg
Description: Outlet

Crossing ID: WC_0758

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 15, 2018

Watercourse Name: Atim Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 303,983 | **Northing:** 5,938,005

Stream Classification: Non-Fluvial

Bankfull Width: 2m (Estimated to Nearest Metre) **Crossing Type:** Culvert - Multiple

Erosion at Site: No

Structural Problems: None

Culvert(s) Diameter: 1) 1 m
2) 1 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown

Substrate Type: none

For what length of culvert?: unknown

What proportion has backwater?:

50%

Culvert Slope: Level and Uniform

Embedded?: no

Outlet Gap: 0.4 m

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: Serious Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Unidentified minnows were noted downstream of culvert 2. There is an outlet gap of 0.4 meters at these culvert. These minnows could not utilize this culvert for habitat connectivity.

Crossing ID: WC_0784



Photo No.: Photos-20180515-202707.jpg
Description: Culvert 1 - Inlet



Photo No.: Photos-20180515-202832.jpg
Description: Culvert 1 - Upstream



Photo No.: Photos-20180515-202856.jpg
Description: Culvert 2 - Inlet



Photo No.: Photos-20180515-202947.jpg
Description: Culvert 2 - Upstream



Photo No.: Photos-20180515-203006.jpg
Description: Culvert 2 - Downstream



Photo No.: Photos-20180515-203052.jpg
Description: Culvert 2 - Outlet

Crossing ID: WC_0784

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180515-203101.jpg
Description: Culvert 1 - Downstream

Crossing ID: WC_0784

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 09, 2018

Watercourse Name: Kilini Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 683,851 | **Northing:** 5,939,586

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 2m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Culvert(s) Diameter: 1) 2.7 m

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Inlet

Erosion Source: Other (rip rap slipped)

Erosion Extent: Low

Total Erosion Area: 2 m²

Structural Problems: None

Greater than 10% of the culvert diameter blocked by debris?: Yes

Substrate in Culvert?: unknown

Substrate Type: unknown

For what length of culvert?: unknown

What proportion has backwater?: 50%

Culvert Slope: level and uniform

Outlet Gap: none

Embedded?: unknown

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Inlet of WC_0775. Wetlands upstream, hard to determine channel. Riprap has slipped into water and is causing some concerns for fish passage with low water levels and/or low flow. No way to determine if culvert is embedded or not.

Crossing ID: WC_0789




Photo No.: Photos-20180509-213309.jpg
Description: Inlet / Erosion



Photo No.: Photos-20180509-213347.jpg
Description: Upstream

Crossing ID: WC_0789

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 09, 2018

Watercourse Name: Killini Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 683,878 | **Northing:** 5,939,587

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 2m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Erosion at Site: No

Structural Problems: None

Culvert(s) Diameter: 1) 2.7 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 50%

Culvert Slope: level and uniform

Outlet Gap: none

Embedded?: unknown

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Inlet of WC_0789. wetland surrounding area hard to define channel. Construction occurred in this area recently, believe the culvert was replaced here when the highway was redone. Culvert is sticking out into water 2 feet past riprap. water is now along the outside of the culvert.

Crossing ID: WC_0775

NSW Sturgeon River Watercourse Assessment



Photo No.: Photos-20180509-212037.jpg
Description: Outlet



Photo No.: Photos-20180509-212204.jpg
Description: Downstream Area



Photo No.: Photos-20180509-212433.jpg
Description: Wetland Downstream

Crossing ID: WC_0775

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 09, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 639,959 | **Northing:** 5,938,896

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 7m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Bank Slump, Fill Slope

Erosion Extent: High **Total Erosion Area:** 8 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 16 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Log Pilings

Abutment Functioning?: No, Materials eroding from under due to erosion

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: Vegetation

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: Yes, damaged guardrail

Bridge Signs: Yes, sign is present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Slumping and fill slope erosion is exposing abutment walls

Crossing ID: WC_0798



Photo No.: Photos-20180509-190359.jpg
Description: Upstream



Photo No.: Photos-20180509-190431.jpg
Description: Inlet



Photo No.: Photos-20180509-190525.jpg
Description: Slumping



Photo No.: Photos-20180509-190701.jpg
Description: Downstream



Photo No.: Photos-20180509-190741.jpg
Description: Outlet



Photo No.: Photos-20180509-191039.jpg
Description: Deck

Crossing ID: WC_0798

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 14, 2018

Watercourse Name: Kilini Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 683,491 | **Northing:** 5,939,269

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 8m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Erosion at Site: No

Structural Problems: Other - Rusting & undersized culvert

Culvert(s) Diameter: 1) 2.2 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: No **Substrate Type:** None

For what length of culvert?: unknown

What proportion has backwater?: 25%

Culvert Slope: Level and Uniform

Outlet Gap: n/a

Embedded?: no

Pool Depth: 0.4 m

Scour pool apparent?: No

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Inlet of culvert, outlet is WC_0790. Upstream and downstream is a wetland area. Highway 770 just redone. Silt fencing from the start of construction still present, not in great shape.

Crossing ID: WC_0800



Photo No.: Photos-20180514-153206.jpg
Description: Upstream



Photo No.: Photos-20180514-153253.jpg
Description: Inlet

Crossing ID: WC_0800

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 14, 2018

Watercourse Name: Kilini Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 683,491 | **Northing:** 5,939,281

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 4m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Outlet

Erosion Source: Bank Slump **Erosion Extent:** Low

Structural Problems: Yes - undersized culvert.

Culvert(s) Diameter: 1) 2.2 m

Total Erosion Area: 2 m²

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 100%

Culvert Slope: Level and Uniform

Outlet Gap: none

Pool Depth: none

Embedded?: no

Scour pool apparent?: No

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Outlet of WC_0800. opens into a wetland. lots of veg on top of culvert. vehicle tracks on fill slope,

Crossing ID: WC_0790



Photo No.: Photos-20180514-152222.jpg
Description: Downstream



Photo No.: Photos-20180514-152244.jpg
Description: Outlet



Photo No.: Photos-20180514-152308.jpg
Description: Erosion

Crossing ID: WC_0790

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 15, 2018

Watercourse Name: Atim Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 303,580 | **Northing:** 5,936,582

Stream Classification: Non-Fluvial

Bankfull Width: 2m (Estimated to Nearest Metre) **Crossing Type:** Culvert - Single

Erosion at Site: No

Structural Problems: None

Culvert(s) Diameter: 1) 3 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: <25%

Culvert Slope: Level and Uniform

Outlet Gap: none

Embedded?: No

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Outlet of WC_0836. Unable to see into culvert due to fencing. Inlet has cement structure surrounding culvert while the outlet does not. Concerns with backwater. Erosion control is good.

Crossing ID: WC_0817



Photo No.: Photos-20180515-195432.jpg
Description: Smaller culvert



Photo No.: Photos-20180515-195511.jpg
Description: Downstream



Photo No.: Photos-20180515-195528.jpg
Description: Outlet

Crossing ID: WC_0817

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 15, 2018

Watercourse Name: Atim Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 303,578 | **Northing:** 5,936,567

Stream Classification: Non-Fluvial

Bankfull Width: 2m (Estimated to Nearest Metre) **Crossing Type:** Culvert - Single

Erosion at Site: No

Structural Problems: None

Culvert(s) Diameter: 1) 3 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Some **Substrate Type:** stream bed

For what length of culvert?: 1m

What proportion has backwater?: <25%

Culvert Slope: Level and Uniform

Embedded?: No, not purposefully

Outlet Gap: none

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Inlet for WC_0817. Movement of stream bed into culvert. Material moved there has grown some vegetation. Low water levels, low backwater.

Crossing ID: WC_0836

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180515-194548.jpg
Description: Upstream



Photo No.: Photos-20180515-194614.jpg
Description: Inlet

Crossing ID: WC_0836

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 09, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 638,994 | **Northing:** 5,937,784

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 5m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Potential **Erosion Location (Inlet or Outlet):** Both

Erosion Source: Other (sedimentation around wing walls)

Erosion Extent: Low **Total Erosion Area:** 8 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 6 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: No, materials moving around walls

Armour: None

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: Yes, wingwall functioning

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Unable to determine structural integrity of bridge due to capacity of water to bridge. Water is in contact with treated wood abutment and wing walls.

Crossing ID: WC_0819



Photo No.: Photos-20180509-181815.jpg
Description: Upstream



Photo No.: Photos-20180509-181823.jpg
Description: Inlet



Photo No.: Photos-20180509-181905.jpg
Description: Downstream



Photo No.: Photos-20180509-181930.jpg
Description: Outlet



Photo No.: Photos-20180509-182019.jpg
Description: Deck



Photo No.: Photos-20180509-182050.jpg
Description: Increasing sedimentation around wing walls

Crossing ID: WC_0819

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180509-182126.jpg
Description: Golf course bridge 5m south of road bridge

Crossing ID: WC_0819

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 09, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 635,249 | **Northing:** 5,932,493

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 4m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Potential **Erosion Location (Inlet or Outlet):** Inlet

Erosion Source: Other (missing wingwall)

Erosion Extent: Low **Total Erosion Area:** 3 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 4 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: No - falling apart and/or materials eroding from underneath

Wingwall Functioning?: No - falling apart and/or materials eroding from underneath

Armour: None

Opening Blockage: 0%

Cause of blockage: Other - none

Structural Problems: Yes, BA,RA,V

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Hoople Lake approx 500m east of bridge with connecting ditch channel on inlet side. Bridge looks very old.

Crossing ID: WC_0865



Photo No.: Photos-20180509-173138.jpg
Description: Upstream



Photo No.: Photos-20180509-173200.jpg
Description: Downstream



Photo No.: Photos-20180509-173220.jpg
Description: Deck



Photo No.: Photos-20180509-173355.jpg
Description: Inlet



Photo No.: Photos-20180509-173431.jpg
Description: Wing wall damage and lack there of wingwall as well rotting on east side top



Photo No.: Photos-20180509-173527.jpg
Description: Outlet

Crossing ID: WC_0865

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 09, 2018

Watercourse Name: Sturgeon River

GPS Co-ordinates:

UTM: 11 | **Easting:** 635,683 | **Northing:** 5,931,220

Stream Classification: Non-Fluvial

Bankfull Width: 1.6m (Measured)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes

Erosion Location (Inlet or Outlet): Both

Erosion Source: Bridge deck

Total Erosion Area: 3m²

Erosion Extent: low

Most Common Bridge Substructure Material: Timber

Total Deck Length: 6 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: No - falling apart and/or materials eroding from underneath

Armour: Riprap

Opening Blockage: 10%

Cause of blockage: Other - rip rap

Structural Problems: Yes, Other - Wingwall separating from bridge

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Large rocks in stream channel at inlet and outlet. Rocks were strategically placed there in the form of rip rap. Water is passing through, however this is a fish passage concern, since larger fish will not be able to get through the holes between rocks. 2/4 grader markers have damage (bullet holes). Open decking pattern has resulted in road surface material entering the stream under the bridge.

Crossing ID: WC_0868



Photo No.: Photos-20180509-170018.jpg
Description: Upstream



Photo No.: Photos-20180509-170113.jpg
Description: Inlet



Photo No.: Photos-20180509-170157.jpg
Description: Downstream



Photo No.: Photos-20180509-170243.jpg
Description: Outlet



Photo No.: Photos-20180509-170616.jpg
Description: Wing wall SE slanting



Photo No.: Photos-20180509-170754.jpg
Description: 10% blockage inlet concerns

Crossing ID: WC_0868

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180509-171026.jpg
Description: Deck

Crossing ID: WC_0868

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 15, 2018

Watercourse Name: Atim Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 303,005 | **Northing:** 5,930,098

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 2m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Erosion at Site: No

Structural Problems: Yes, undersized culvert

Culvert(s) Diameter: 1) 1.5 m

Greater than 10% of the culvert diameter blocked by debris?: Yes

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 100%

Culvert Slope: Level and Uniform

Outlet Gap: none

Embedded?: no

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Grate placed on inlet of culvert. Organic debris accumulating. Grate mesh is small and will not allow for larger fish to pass through.

Crossing ID: WC_0871

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180515-170534.jpg
Description: Upstream



Photo No.: Photos-20180515-170602.jpg
Description: Inlet



Photo No.: Photos-20180515-170633.jpg
Description: Downstream



Photo No.: Photos-20180515-170701.jpg
Description: Outlet



Photo No.: Photos-20180515-171112.jpg
Description: Grate

Crossing ID: WC_0871

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 15, 2018

Watercourse Name: Atim Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 302,004 | **Northing:** 5,929,365

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 5m (Estimated to Nearest Metre)

Crossing Type: Culvert - Single

Culvert(s) Diameter: 1) 1.5 m

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Outlet

Erosion Source: Ditch Gully

Erosion Extent: Low **Total Erosion Area:** 2 m²

Greater than 10% of the culvert diameter blocked by debris?: Yes

Substrate in Culvert?: Unknown **Substrate Type:** Unknown

For what length of culvert?: Unknown

What proportion has backwater?: 50%

Culvert Slope: level and uniform

Outlet Gap: none

Embedded?: No

Pool Depth: none

Scour pool apparent?: No

Structural Problems: None

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Grate on inlet of culvert. Organic debris built up on grate causing fish passage concerns.

Crossing ID: WC_0872

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180515-164842.jpg
Description: Upstream



Photo No.: Photos-20180515-164942.jpg
Description: Inlet / waffle style grate



Photo No.: Photos-20180515-165031.jpg
Description: Downstream



Photo No.: Photos-20180515-165056.jpg
Description: Outlet



Photo No.: Photos-20180515-165231.jpg
Description: Erosion

Crossing ID: WC_0872

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 15, 2018

Watercourse Name: Atim Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 699,009 | **Northing:** 5,928,264

Stream Classification: Non-Fluvial

Bankfull Width: 1m (Estimated to Nearest

Metre) **Crossing Type:** Bridge - Permanent

Erosion at Site: No

Most Common Bridge Substructure Material: Timber

Total Deck Length: 3 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Closed

Curb Type: Concrete

Road Surface Material: Other - pavement

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: Other - planks of lumber

Opening Blockage: 0%

Cause of blockage: Other - steel wall from culverts beside

Structural Problems: None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Damaged, sign is either down or needs to be replaced

Fish Passage Assessment: Some Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: down stream from 2 culverts and a steel wall holding water back upstream. Low flow

Crossing ID: WC_0875

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180515-162301.jpg
Description: Upstream



Photo No.: Photos-20180515-162320.jpg
Description: Inlet



Photo No.: Photos-20180515-162514.jpg
Description: Downstream




Photo No.: Photos-20180515-162544.jpg
Description: Outlet



Photo No.: Photos-20180515-163027.jpg
Description: Lumber amour

Crossing ID: WC_0875

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 09, 2018
Watercourse Name: Sturgeon River
GPS Co-ordinates:
 UTM: 11 | Easting: 636,760 | Northing: 5,928,008

Stream Classification: Non-Fluvial
Bankfull Width: 1m (Measured)
Crossing Type: Culvert - Multiple
Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Outlet
Erosion Source: Bank Slump
Erosion Extent: Low **Total Erosion Area:** 3 m²
Structural Problems: None
Greater than 10% of the culvert diameter blocked by debris?: No
Substrate in Culvert?: unknown **Substrate Type:** unknown
For what length of culvert?: unknown
What proportion has backwater?: <25%
Culvert Slope: Sloped and not uniform
Outlet Gap: none **Embedded?:** No
Pool Depth: none **Scour pool apparent?:** No

Culvert(s) Diameter: 1) 0.8 m
 2) 0.8 m

Fish Passage Assessment: Serious Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Inlets are about 30 meters apart but the outlets are within a meter of each other. Erosion is caused by slumping around outlets. Inlet gap noted at the east inlet. There is some blockage on the west inlet with large rocks. Outlet east has an accumulation of organic debris causing some blockage.

Crossing ID: WC_0877



Photo No.: Photos-20180509-163349.jpg
Description: Outlets



Photo No.: Photos-20180509-163404.jpg
Description: Downstream



Photo No.: Photos-20180509-163731.jpg
Description: Upstream west



Photo No.: Photos-20180509-163844.jpg
Description: Inlet west



Photo No.: Photos-20180509-164137.jpg
Description: Upstream east



Photo No.: Photos-20180509-164214.jpg
Description: Inlet east

Crossing ID: WC_0877

NSW Sturgeon River Watercourse Assessment



Inspection Date: May 08, 2018

Watercourse Name: Riviere Qui Barre

GPS Co-ordinates:

UTM: 12 | **Easting:** 304,103 | **Northing:** 5,975,450

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 7m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Outlet

Erosion Source: Ditch Gully **Total Erosion Area:** 1 m²

Erosion Extent: Low

Most Common Bridge Substructure Material: Timber

Total Deck Length: 7 m

Deck Width (Number of Lanes): 2

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - but earth moving around the walls

Armour: None

Opening Blockage: 0% **Structural Problems:** None

Bridge Signs: No, sign is not present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Tributary water height is touching the wooden abutments, no armour protecting wood and earth from movement into stream. Fence crossing creek could lead to blockage of opening. Earth is moving around the outer portion of the inlet wingwalls. Treated timber within aquatic habitat.

Crossing ID: WC_0053

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180508-172849.jpg
Description: Upstream



Photo No.: Photos-20180508-173006.jpg
Description: Inlet



Photo No.: Photos-20180508-173323.jpg
Description: Downstream



Photo No.: Photos-20180508-173422.jpg
Description: Outlet



Photo No.: Photos-20180508-173516.jpg
Description: Deck

Crossing ID: WC_0053

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 18, 2018

Watercourse Name: Carrot Creek

GPS Co-ordinates:

UTM: 12 | **Easting:** 324,165 | **Northing:** 5,954,070

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 3m (Estimated to Nearest Metre)

Crossing Type: Culvert - Multiple

Erosion at Site: No

Structural Problems: Yes, undersized culverts

Culvert(s) Diameter: 1) 1.25 m
2) 1.25 m

Greater than 10% of the culvert diameter blocked by debris?: No

Substrate in Culvert?: Unknown **Substrate Type:** unknown

For what length of culvert?: unknown

What proportion has backwater?: 75%

Culvert Slope: Level and Uniform

Outlet Gap: none

Embedded?: no

Pool Depth: none

Scour pool apparent?: No

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Downstream channel is hard to determine (dissipates into wetland?). Pooling occurring near culverts, possibly due to undersized culverts and low flow.

Crossing ID: WC_0335

NSWA Sturgeon River Watercourse Assessment



Photo No.: Photos-20180518-164812.jpg
Description: Downstream



Photo No.: Photos-20180518-164848.jpg
Description: Downstream



Photo No.: Photos-20180518-164958.jpg
Description: Ditch gully flows into Downstream



Photo No.: Photos-20180518-165022.jpg
Description: Outlet



Photo No.: Photos-20180518-165044.jpg
Description: Upstream



Photo No.: Photos-20180518-165100.jpg
Description: Inlet

Crossing ID: WC_0335

NSW Sturgeon River Watercourse Assessment



Photo No.: Photos-20180518-165117.jpg
Description: Inlet

Crossing ID: WC_0335

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 11, 2018
Watercourse Name: Sturgeon River
GPD Co-ordinates:
 UTM: 11 | Easting: 657,729 | Northing: 5,949,149

Stream Classification: Fluvial (Permanent - Large)
Bankfull Width: 20m (Estimated to Nearest Metre)
Crossing Type: Bridge - Permanent
Erosion at Site: Yes **Erosion Location (Inlet or Outlet):** Both
Erosion Source: Fill Slope
Erosion Extent: Low **Total Erosion Area:** 36 m²

Most Common Bridge Substructure Material: Timber
Total Deck Length: 16 m
Deck Width (Number of Lanes): 2
Decking Material: Concrete
Decking Pattern: Closed
Curb Type: Concrete
Road Surface Material: Other - pavement
Abutment Type: Log Pilings
Abutment Functioning?: Yes - in good condition and no materials eroding from underneath
Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath
Armour: None
Opening Blockage: 0%
Cause of blockage: Other - none
Structural Problems: None
Bridge Signs: Yes, sign is present
Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns
Emergency Repair Required?: No
Overall Risk: Medium
Comments: Steep fill slope gradient is resulting in erosion. Small hole noted in bridge deck.

Crossing ID: WC_0540



Photo No.: Photos-20180511-163052.jpg
Description: Deck



Photo No.: Photos-20180511-163136.jpg
Description: Upstream



Photo No.: Photos-20180511-163226.jpg
Description: Inlet



Photo No.: Photos-20180511-163455.jpg
Description: Downstream



Photo No.: Photos-20180511-163508.jpg
Description: Outlet



Photo No.: Photos-20180511-163730.jpg
Description: Erosion

Crossing ID: WC_0540

NSW Sturgeon River Watercourse Assessment



Photo No.: Photos-20180511-163750.jpg
Description: Erosion

Crossing ID: WC_0540

NSWA Sturgeon River Watercourse Assessment



Inspection Date: May 14, 2018

Watercourse Name: Kilini Creek

GPS Co-ordinates:

UTM: 11 | **Easting:** 689,040 | **Northing:** 5,945,983

Stream Classification: Fluvial (Permanent - Small)

Bankfull Width: 10m (Estimated to Nearest Metre)

Crossing Type: Bridge - Permanent

Culvert(s) Diameter: n/a

Erosion at Site: Yes | **Erosion Location (Inlet or Outlet):** Outlet

Erosion Source: Bridge Deck, Other (lots of gravel from roads creating a mound under the bridge)

Erosion Extent: Low | **Total Erosion Area:** 2 m²

Most Common Bridge Substructure Material: Timber

Total Deck Length: 5 m

Deck Width (Number of Lanes): 1

Decking Material: Concrete

Decking Pattern: Open

Curb Type: Concrete

Road Surface Material: Gravel

Abutment Type: Log Pilings

Abutment Functioning?: Yes - in good condition and no materials eroding from underneath

Wingwall Functioning?: Yes - in good condition and no materials eroding from underneath

Armour: None

Opening Blockage: 0%

Cause of blockage: Road Material

Structural Problems: None

Bridge Signs: Yes, sign is present

Grader markers or bridge reflectors?: Yes, sign is present

Fish Passage Assessment: No Concerns

Emergency Repair Required?: No

Overall Risk: Medium

Comments: Bridge is at water capacity and the integrity of structure is unknown. Road material is in streambed.

Crossing ID: WC_0611